These mounting instructions are valid for the scanning head LIF 98W (ID 1184920-xx) and the scale 902W (ID 658739-01)

Warnings


AK LIF 9xW

Klasse 3R: bei nicht angebauten AK LIF 9x W, mit Spannung versorgt


Class 3R: When AK 9x W is not mounted and is under power

Klasse 1: bei korrekten Anbau des AK LIF 9xW

Class 1: When the AK LIF 9x W is properly mounted





Invisible laser radiation
Avoid direct exposure to beam
Laser class 3R
SEE INSTRUCTION BELOW
IEC 60825-1:1993+A2:2001
P< 4mW λ= 850 nm



Teilung nicht berühren!

Do not touch the graduation!





Edited on:

Z Z Z	Change-No.		Created	Responsible	Released		Version	Rev.	Sheet	Page
	C056927-05	Name	Schäfer	Schäfer	Bauer	D1215163	- 00 -	- A -	- 01	1/
	Serie	Date	25.04.2017	25.04.2017	25.04.2017	Doc	ument no.			12

Items Supplied



Figure 1: LIF 98W scanning head covered in shielding bag




Figure 2: LIF 98W scanning head (ID 1184920-xx)



Figure 3: LIF 902W scale (ID 658739-01)



Figure 4: LIF 9x2 mounting aid

Change No.		Created	Responsible	Released		Version	Rev.	Sheet	Page
C056927-05	Name	Schäfer	Schäfer	Bauer	D1215163	- 00 -	· A ·	- 01	2/
Serie	Date	25.04.2017	25.04.2017	25.04.2017	Doc	ument no.			12

Mounting the Scale

Remove the scale from the packaging as shown in Figure 5.




Figure 5: Removing the scale

Ensure that the red protective clip remains on the scale. Under no circumstances, never touch the graduation with your fingers (danger of contamination).

In order to align the scale (figures 6 and 7), the top surface and a side surface of the scale holder both serve as supports.




Figure 6: Support surfaces for the scale

Support surfaces for the scale




Figure 7: Aligning the scale

Alignments for the scale

/ -	Change No.		Created	Responsible	Released		Version	Rev.	Sheet	Page
	C056927-05	Name	Schäfer	Schäfer	Bauer	D1215163	- 00 -	Α -	- 01	3/
	Serie	Date	25.04.2017	25.04.2017	25.04.2017	Doc	ument no.			12

Four screws (DIN EN ISO $4762 \text{ M2} \times 6$) are recommended for securing the scale. (Maximum tightening torque: 0.32 Nm).




Figure 8: Securing the scale

Mounting the Scanning Head

Take the scanning head out of the shielding bag



Figure 9: Scanning head with shielding bag

Align the scanning head with the support surface.




Figure 10: Support surface for the scanning head

/ 4	Change No.		Created	Responsible	Released		Version	Rev.	Sheet	Page
	C056927-05	Name	Schäfer	Schäfer	Bauer	D1215163	- 00 -	· A ·	- 01	4/
	Serie	Date	25.04.2017	25.04.2017	25.04.2017	Doc	ument no.			12

Put the head at its approximate position while the protective cover still remains on the scale. Secure the head loosely in order to allow adjustment. Two screws (DIN EN ISO 4762 M2.5 x 20) and two washers (DIN EN ISO 7092 2.5) are recommended for securing the scanning head.




Figure 11: Pre-positioned scanning head

Remove the protective clip.




Figure 12: Removal of the protective clip

Set the scanning gap and the distance to the rotation center of the LIF 982 with the mounting aid. Ensure that the mounting aid is positioned correctly (Figures 13 and 14) and the scale is rotated into mounting position as shown in dimension drawing (2.8° tilted to scanning head base)




Figure 13: Correct position LIF 9x2 mounting aid



Figure 14: Incorrect position of the mounting aid

II/ 	Change No.		Created	Responsible	Released		Version	Rev.	Sheet	Page
$\begin{pmatrix} \vec{\lambda}_{\Delta} \end{pmatrix}$	C056927-05	Name	Schäfer	Schäfer	Bauer	D1215163	- 00 -	- A -	- 01	5/
	Serie	Date	25.04.2017	25.04.2017	25.04.2017	Doc	ument no.			12

Press the scanning head to the support alignments and tighten the mounting screws. (Maximum tightening torque: 0.65 Nm).




Figure 15: Securing the scanning head

It must be easy to remove the LIF 9x2 mounting aid from the scanning gap after the scanning head has been mounted.



Figure 16: Removal of the mounting aid

Change No.		Created	Responsible	Released		Version	Rev.	Sheet	Page
C056927-05	Name	Schäfer	Schäfer	Bauer	D1215163	- 00 -	- A -	- 01	6/
Serie	Date	25.04.2017	25.04.2017	25.04.2017	Doc	ument no.			12

Adjusting the Output Signals

A PWM8 phase-angle measuring unit from HEIDENHAIN (Id. Nr. 309 956-xx), for example, along with a connecting cable (Id. Nr. 331 693-xx) and oscilloscope, is suited for adjusting the output signals.




Figure 17: Accessories for adjustment

Remove the protective cap on the plug of the adapter connector, and remove the cover.




Figure 18: Opened adapter connector

II/ - 	Change No.		Created	Responsible	Released		Version	Rev.	Sheet	Page
$\begin{pmatrix} \vec{\lambda}_{\vec{\Delta}} \end{pmatrix}$	C056927-05	Name	Schäfer	Schäfer	Bauer	D1215163	- 00 -	· A ·	- 01	7/
	Serie	Date	25.04.2017	25.04.2017	25.04.2017	Doc	ument no.			12

Use the adapter cable (331 693-xx) to connect the LIF 982W to the PWM8, and the BNC outputs of the PWM with the oscilloscope.




Figure 19: Adjustment setup

The PWM8 displays the signals as shown below.




Figure 20: Display of the signals on the PWM8

/ 4 \	Change No.		Created	Responsible	Released		Version	Rev.	Sheet	Page
	C056927-05	Name	Schäfer	Schäfer	Bauer	D1215163	- 00 -	· A ·	- 01	8/
	Serie	Date	25.04.2017	25.04.2017	25.04.2017	Doc	ument no.			12

The signals can also be displayed on the oscilloscope as follows:




Figure 21: Incremental signal display on the oscilloscope




Figure 22: Reference signal display on the oscilloscope

Five potentiometers and one DIP-switch are available on the adapter connector for adjusting the signals.






Figure 23: APE PCB with potentiometers

	Change No.		Created	Responsible	Released		Version	Rev.	Sheet	Page
$\begin{pmatrix} \vec{\lambda}_{\Delta} \end{pmatrix}$	C056927-05	Name	Schäfer	Schäfer	Bauer	D1215163	- 00 -	- A -	- 01	9/
	Serie	Date	25.04.2017	25.04.2017	25.04.2017	Doc	ument no.			12

The following values are to be checked	d and/or set:			
Signal values	Initial operation	Fine adjustment	Typical values*1)	
Signal levels M _A , M _B (0°, 90°)*2)	0.81.2 V _{pp}	Not possible	0.61.2 V _{pp}	_
Amplitude ratio M _A / M _B	0.8 1.25	0.95 1.05	0.95 1.05	P5
Phase angle PHA	90° ± 10°	90° ± 5°	90° ± 3°	P4
On-off ratio TV _A and TV _B	0° ± 15 °	0° ± 5 °	0° ± 3 °	P2 *3)
$TV = 2 \arcsin (P - N / M)$				P3 *3)
Usable component G	0.20.85 V _{pp}	0.20.85 V _{pp}	0.20.85 V _{pp}	
Switching threshold E	0.2·G 0.7·G	0.2·G 0.7·G	0.2·G 0.7·G	
Zero crossovers K, L	180° ± 90° el.	180° ± 45° el.	180° ± 45° el.	P1
(K-L) / 2	< 90°	< 60°	< 60°	S1 *3)

^{*1)} Typically, these values can be achieved by accurate mechanical mounting and fine adjustment by potentiometers and DIP-switch. The values are valid up to 20% of the -3dB cut-off frequency in permissible ranges of temperature, supply voltage and, mounting tolerances.

 $^{^{\}star3)}$ S1 is shifting the reference signal position in 90° steps. In consideration of the tolerance of the Ref. signal, this allows to adjust the value |(K-L) / 2| < 60°. Depending on the setting of S1, the Ref. signal is shifted and the allocation of TV₁ and TV₂ to P2 and P3 is as follows:

S1 setting	Z O L	Z N C O	Z O V	I O I
Ref. signal shift	0°	-90°	+90°	180°
TV _x / Px	$TV_1 = P2$	$TV_1 = P3$	$TV_1 = P3$	$TV_1 = P2$
allocation	$TV_2 = P3$	$TV_2 = P2$	$TV_2 = P2$	$TV_2 = P3$

When reassembling the adapter connector, ensure that no cable wires are crimped.





Figure 24: Assembly of the connector

II / - 1	Change No.		Created	Responsible	Released		Version	Rev.	Sheet	Page
$\begin{pmatrix} \vec{\lambda}_{\vec{\Delta}} \end{pmatrix}$	C056927-05	Name	Schäfer	Schäfer	Bauer	D1215163	- 00 -	- A -	- 01	10/
	Serie	Date	25.04.2017	25.04.2017	25.04.2017	Doc	ument no.			12


^{*2)} Recommended signal level for lower fault detection limit 0.3 Vpp / upper fault detection limit 1.35 Vpp

Electrical Connection




Electrical Data

Power supply



Output signals



/ / \	Change No.		Created	Responsible	Released		Version	Rev.	Sheet	Page
	C056927-05	Name	Schäfer	Schäfer	Bauer	D1215163	- 00 -	· A ·	- 01	11/
	Serie	Date	25.04.2017	25.04.2017	25.04.2017	Document no.			12	

Cleaning

You must always ensure that the encoder is protected from contamination during both mounting and operation. If the encoder must be cleaned, the following must be kept in mind:

There are no optical components inside the scanning head that can be accessed from the outside. The graduated scale is exposed in its holder, meaning that it might become necessary to clean the scale. Dust particles should not be wiped off, but rather blown off with dry, oil-free pressurized air. An ultrasonic bath is recommended for removing organic contaminations (e.g., fingerprints). Good cleaning results can be achieved in a cleaning bath with demineralized water and dishwashing detergent available off the shelf, at approx. 40 °C (104 °F) and 35 kHz.



Figure 24: Ultrasonic cleaning bath

The parts should be placed in a basket and completely submerged in the cleaning liquid, as shown in figure below. The glass must not come into contact with other parts during cleaning, since it might become damaged.



Figure 25: Scale in a basket in the ultrasonic cleaning bath

A treatment of approx. three minutes is recommended. The scale should then be rinsed with demineralized water and be blown dry with dry, oil-free pressurized air.

I/ / \	Change No.		Created	Responsible	Released		Version	Rev.	Sheet	Page
$\left(\begin{array}{c} \Delta_{\Delta} \\ \Delta_{\Delta} \end{array}\right)$	C056927-05	Name	Schäfer	Schäfer	Bauer	D1215163	- 00 -	- A -	- 01	12/
	Serie	Date	25.04.2017	25.04.2017	25.04.2017	Document no.			12	