



M = machine guideway / Maschinenführung
 ML = measuring length / Messlänge
 G = gauging points / Messpunkte
 $\langle \rangle = 0 \dots ML$
 A = cable / Anschlusskabel

K = customer mounting dimensions / kundenseitige Anschlussmaße

optional / Optionen
 P = M5 air inlet / M5 Luftanschluss
 S1, S2 = switch signals / Schaltsignale
 RI = selectable reference mark / wählbare Referenzmarke
 * = actuator magnet / Schaltmagnet
 ** = sensor position / Sensorposition

Original drawing		MSA770		ID number: -
Scale	Format	MSA770		Change No. C157360-16
Dimensions in mm	1:1	A2	Anschlussmaße / Mating Dimensions	Phase: Serie
Tolerances as per ISO 8015				General Tolerances ISO 2768:1989-mH ≤ 6:±0.2
The reproduction, distribution and utilization of this document as well as the communication of its contents to others without express authorization is prohibited. Offenders will be held liable for the payment of damages. All rights reserved in the event of a patent, utility model or design. (ISO 16016)				
Released		Version	Revision	Sheet
23.11.2023		D 670864-01-A-01		1 of 1
www.rsfs.at		Document number		