

Abtasteinheit
Scanning Unit
Tête caprice
Testina
Cabezal

HEIDENHAIN

Austauschanleitung
Replacing Instructions
Instructions de montage
Istruzioni per la sostituzione
Instrucciones de sustitución

LS 103

LS 183


LF 103

LF 183









1.




2.











DIN EN 100 015 - 1
CECC 00015 - 1
















Id.-Nr. 200 417-02






$M_d = 0.6 \text{ Nm}$





DIN EN 100 015 - 1
CECC 00015 - 1





HEIDENHAIN

DR. JOHANNES HEIDENHAIN GmbH

Dr.-Johannes-Heidenhain-Straße 5

83301 Traunreut, Germany

☎ +49 (8669) 31-0

FAX +49 (8669) 50 61

E-Mail: info@heidenhain.de

Technical support FAX +49 (8669) 31-10 00

Measuring systems ☎ +49 (8669) 31-31 04

E-Mail: service.ms-support@heidenhain.de

TNC support ☎ +49 (8669) 31-31 01

E-Mail: service.nc-support@heidenhain.de

NC programming ☎ +49 (8669) 31-31 03

E-Mail: service.nc-pgm@heidenhain.de

PLC programming ☎ +49 (8669) 31-31 02

E-Mail: service.plc@heidenhain.de

Lathe controls ☎ +49 (7 11) 95 28 03-0

E-Mail: service.hsf@heidenhain.de

www.heidenhain.de



Ve 00

297 021-92 · 1,5 · 5/2006 · E · Printed in Germany

Änderungen vorbehalten · *Subject to change without notice* · Sous réserve de modifications · *Con riserva di modifiche* · Sujeto a modificaciones

